

CONTENTS

Title	i
Certificate of Approval	iii
Certificate from Supervisors	v
Declaration	vii
Acknowledgement	ix
Abstract	xi
Contents	xiii
List of Abbreviations	xix
List of Symbols	xxi
List of Figures	xxv
List of Tables	xxxiii
Chapter 1	
Introduction	1
Chapter 2	
Literature Review: Mechanical Activation of Al-Oxyhydroxide Minerals	5
2.0 Introduction	5
2.1 General Overview	5
2.1.1 Historical	5
2.1.2 Mechanical Activation – Fundamental Aspects	6
2.1.2.1 Comminution and mechanical activation of solids	7
2.1.2.2 Physicochemical changes during milling	10
2.1.2.3 Thermodynamic and crystal chemistry perspective	12
2.1.3 Mechanically Induced Reactivity	13
2.1.3.1 Select examples	15
2.1.4 Milling Devices for Mechanical Activation	18
2.1.4.1 Milling mechanism	18
2.1.4.2 Milling energy	20
2.1.4.3 Milling environment	20
2.1.4.4 Choice of the milling device	21
2.1.5 Physicochemical Changes and Characterisation Techniques	22
2.2 Mechanical Activation of Aluminium Oxyhydroxides	23
2.2.1 Introduction to Al-Oxyhydroxide Minerals	25
2.2.1.1 General	25
2.2.1.2 Gibbsite and boehmite	25
<i>Structure of gibbsite</i>	26
<i>Structure of boehmite</i>	26

2.2.2	Stability	27
2.2.2.1	Stability in water	27
2.2.2.2	Stability in alkali solution	29
2.2.3	Mechanical Activation of Gibbsite and Boehmite	30
2.2.3.1	Mechanical activation of gibbsite	33
	<i>Breakage</i>	33
	<i>Structural changes and phase transformations</i>	35
	<i>Thermal transformations</i>	37
	<i>Leachability</i>	38
2.2.3.2	Mechanical activation of boehmite	39
	<i>Breakage</i>	39
	<i>Structural changes</i>	39
	<i>Thermal transformations</i>	41
	<i>Leachability</i>	42
	<i>Mechanical activation in Bayer process leaching operation</i>	42
2.3	Research Gaps and Scope of the Current Research	45
2.3.1	Research Gaps	45
2.3.1.1	Mechanical activation and reactivity of gibbsite	45
2.3.1.2	Mechanical activation and reactivity of boehmite	47
2.3.2	Scope of the Research	48
Chapter 3		
Materials and Methods		51
3.0	Introduction	51
3.1	Materials	52
3.1.1	Gibbsite	52
3.1.2	Boehmite	52
3.2	Methods	53
3.2.1	Mechanical Activation	53
3.2.1.1	Planetary milling	53
3.2.1.2	Attrition milling	54
3.2.2	Characterisation	55
3.2.2.1	Particulate characterisation	55
	<i>Particle size distribution</i>	55
	<i>Specific surface area and pore size distribution</i>	56
	<i>Morphology</i>	57
	<i>Surface charge</i>	58
3.2.2.2	Structural characterisation	58
	<i>X-ray diffraction (XRD)</i>	58
	<i>Fourier transform infrared (FTIR) spectroscopy</i>	60
	<i>Transmission electron microscopy (TEM)</i>	60
	<i>Thermal Analysis</i>	60

3.2.3	Leaching	61
3.2.3.1	Procedure	61
3.2.3.2	Characterisation of leach residues	62
3.2.4	Assessment of the Reactivity of Boehmite	62
3.2.4.1	Boehmite to γ -Al ₂ O ₃ thermal transformation	62
3.2.4.2	Leaching kinetics	63
3.2.4.3	Correlations between physicochemical characteristics and reactivity	63

Chapter 4

Mechanical Activation, Physicochemical Characterisation and Reactivity of Gibbsite [γ-Al(OH)₃]		65
4.0	Introduction	65
4.1	Mechanical Activation of Gibbsite in Planetary Mill	65
4.1.1	Results	66
4.1.1.1	Particle size distribution (PSD)	66
4.1.1.2	Specific surface area and pore size distribution	68
4.1.1.3	Morphology	71
4.1.1.4	X-ray diffraction (XRD)	72
4.1.1.5	Fourier transform infrared (FTIR) spectroscopy	73
4.1.1.6	Transmission electron microscopy (TEM)	75
4.1.1.7	Thermal analysis	76
4.1.1.8	Alkali dissolution	78
4.1.1.9	Reactivity of gibbsite and its correlation with physicochemical characteristics	79
4.1.2	Discussion	81
4.1.2.1	Particulate characteristics of milled gibbsite	81
4.1.2.2	Structural changes in gibbsite during planetary milling	83
4.1.2.3	Reactivity and its correlations with physicochemical characteristics	84
4.2	Mechanical Activation of Gibbsite in Attrition Mill	85
4.2.1	Results	86
4.2.1.1	Particle size distribution	86
4.2.1.2	Specific surface area	88
4.2.1.3	Morphology	88
4.2.1.4	X-ray diffraction (XRD)	89
	<i>Interaction among minerals during high energy milling</i>	90
4.2.1.5	Fourier transform infrared (FTIR) spectroscopy	91
4.2.1.6	Thermal Analysis	92
4.2.1.7	Alkali leaching	93
4.2.1.8	Reactivity and its correlations with physicochemical parameters	94

4.2.1.9	Surface chemistry	95
4.2.2	Discussion	96
4.2.2.1	Particulate characteristics of milled gibbsite	96
4.2.2.2	Structural changes in gibbsite during attrition milling	96
4.2.2.3	Surface chemistry	98
4.3	High Energy Milling of Gibbsite in Planetary and Attrition Mills – A Comparison	99
4.3.1	Size Reduction	101
4.3.2	Structural Changes	102
4.3.3	Reactivity	102

Chapter 5

Mechanical Activation, Physicochemical Characterisation and Reactivity of Boehmite (γ-AlOOH)		103
5.0	Introduction	103
5.1	Mechanical Activation of Boehmite in Planetary Mill	104
5.1.1	Results	104
5.1.1.1	Particle size distribution (PSD)	104
5.1.1.2	Specific surface area and pore size distribution	106
5.1.1.3	Morphology	109
5.1.1.4	X-ray diffraction (XRD)	111
5.1.1.5	Fourier transform infrared (FTIR) spectroscopy	113
5.1.1.6	Transmission electron microscopy (TEM)	114
5.1.1.7	Thermal analysis	116
5.1.1.8	Alkali dissolution	117
5.1.1.9	Reactivity of boehmite and its correlation with physicochemical characteristics	118
5.1.2	Discussion	119
5.1.2.1	Particulate characteristics of attrition milled boehmite	119
5.1.2.2	Structural changes in boehmite during planetary milling	121
5.1.2.3	Reactivity of milled boehmite and correlations with physicochemical characteristics	122
5.2	Mechanical Activation of Boehmite in Attrition Mill	123
5.2.1	Results	124
5.2.1.1	Particle size distribution (PSD)	124
5.2.1.2	X-ray diffraction (XRD)	125
5.2.1.3	Fourier transform infrared (FTIR) spectroscopy	126
5.2.1.4	Thermal analysis	127
5.2.2	Discussion	129
5.2.2.1	Particulate characteristics of attrition milled boehmite	129
5.2.2.2	Structural changes in boehmite during attrition milling	129

5.3	High Energy Milling of Boehmite in Planetary and Attrition Mills – A Comparison	130
-----	---------------------------------------------------------------------------------	-----

Chapter 6

Mechanically Induced Reactivity and Thermal Transformations of Boehmite (γ -AlOOH) 133

6.0	Introduction	133
6.1	Dehydroxylation of Boehmite	133
6.2	Results	136
6.2.1	Thermal Analysis of Unmilled Boehmite	136
6.2.2	Thermal Analysis of Milled Boehmite	137
6.2.2.1	Changes in stage I (upto 100 °C)	137
6.2.2.2	Changes in stage II (100-350 °C) and stage III (350-550 °C)	138
6.2.2.3	Changes in stage IV (above 550 °C)	139
6.2.3	X-ray Diffraction of Heat Treated Boehmite	140
6.2.4	Mechanically Induced Reactivity in Boehmite	141
6.2.4.1	$\alpha_{\text{sample}} - \alpha_{\text{ref}}$ method	143
6.2.4.2	Kinetic data analysis of boehmite to γ -Al ₂ O ₃ transformation	145
	<i>Identification of the reaction mechanism</i>	146
	<i>Kinetic data analysis using nonlinear least square minimisation (NLSM)</i>	150
6.2.5	Correlations between Reactivity and Physicochemical Characteristics	153
6.3	Discussion	155
6.3.1	Changes in Stage I (upto 100 °C)	155
6.3.2	Changes in Stage II (100-350 °C) and Stage III (350-550 °C)	156
6.3.3	Changes in Stage IV (above 550 °C)	158
6.3.4	Reactivity and its Correlations with Physicochemical Characteristics	159
6.3.4.1	$\alpha_{\text{sample}} - \alpha_{\text{ref}}$ method	159
6.3.4.2	Kinetic data analysis	159

Chapter 7

Kinetics of Leaching of Mechanically Activated Boehmite (γ -AlOOH) in Alkali Solutions 163

7.0	Introduction	163
7.1	Leaching Data Collection and Analysis Approach	164
7.2	Leaching of Unmilled Boehmite	166
7.2.1	Results	166
7.2.1.1	α -t plots	166

7.2.1.2	Selection of appropriate kinetic equation	167
7.2.1.3	Estimation of kinetic parameters	168
7.2.1.4	Characterisation of leach residues	171
	<i>Particle size distribution (PSD)</i>	171
	<i>Surface area and pore size distribution</i>	172
	<i>Morphology</i>	174
	<i>Phase analysis</i>	175
7.2.2	Discussion	176
7.2.2.1	Fraction dissolved during leaching	176
7.2.2.2	Leaching mechanism and activation energy	177
7.3	Leaching of Milled Boehmite	180
7.3.1	Results	180
7.3.1.1	α -t plots	180
7.3.1.2	Selection of appropriate kinetic equation	182
7.3.1.3	Estimation of kinetic parameters	183
7.3.1.4	Correlations between kinetic and physicochemical parameters	187
7.3.1.5	Characterisation of leach residues	188
	<i>Particle size distribution (PSD)</i>	188
	<i>Phase analysis</i>	192
7.3.2	Discussion	192
7.3.2.1	Fraction dissolved	192
7.3.2.2	Model fitting and rate constant values	193
7.3.2.3	Activation energy for mechanically activated boehmite	194
7.3.2.4	Leaching mechanism for the activated boehmite	196
 Chapter 8		
Conclusions and Future Scope of Work		199
8.1	Conclusions	199
8.1.1	Mechanical Activation of Gibbsite	199
8.1.2	Mechanical Activation of Boehmite	200
8.1.3	Influence of Mechanical Activation on Thermal Transformations of Boehmite	201
8.1.4	Influence of Mechanical Activation on Boehmite dissolution	202
8.2	Contributions from This Study	202
8.3	Scope of Future Work	203
 References		205
List of Publications from This Study		213
Curriculum Vitae		215